

10/699,825

**WEST Search History**

Hide Items

Restore

Clear

Cancel

DATE: Friday, June 23, 2006

Hide?	<u>Set</u> <u>Name</u>	<u>Query</u>	<u>Hit</u> <u>Count</u>
	<i>DB=PGPB,USPT; PLUR=YES; OP=OR</i>		
<input type="checkbox"/>	L16	l12 or l11	70
<input type="checkbox"/>	L15	l13 and l9	0
<input type="checkbox"/>	L14	(steel and (normalize or normalized or normalizing) and creep and ("coarse carbide" or "creep damage" or haz or "heat affected zone")).clm.	0
<input type="checkbox"/>	L13	L12 not l11	50
<input type="checkbox"/>	L12	(steel and (normalize or normalized or normalizing) and creep and ("coarse carbide" or "creep damage" or haz or "heat affected zone"))	53
<input type="checkbox"/>	L11	(steel and (normalize or normalized or normalizing) and creep and ("type 4" or "type IV"))	20
<input type="checkbox"/>	L10	(steel and (normalize or normalized or normalizing) and creep and ("type 4" or "type IV")).clm.	0
<input type="checkbox"/>	L9	(428/681 or 428/682 or 428/683 or 148/516 or 148/519 or 148/521 or 148/529 or 228/262.41)![CCLS]	1717
	<i>DB=EPAB,JPAB,DWPI; PLUR=YES; OP=OR</i>		
<input type="checkbox"/>	L8	("type 4" or "type IV") and creep and steel and (normalize or normalized or normalizing)	0
<input type="checkbox"/>	L7	l6 or l4	35
<input type="checkbox"/>	L6	L5 not l4	28
<input type="checkbox"/>	L5	steel and (normalize or normalizing) and (haz or "heat affected zone")	29
<input type="checkbox"/>	L4	l2 or l1	7
<input type="checkbox"/>	L3	L2 not l1	5
<input type="checkbox"/>	L2	steel and (haz or "heat affected zone") and ("coarse carbide" or "creep damage")	6
<input type="checkbox"/>	L1	steel and (normalize or normalizing) and ("coarse carbide" or "creep damage")	2

END OF SEARCH HISTORY